Approved For Release 2001/03/04: CIA-RDP80-00809A000500530082-0

U.S. Officials Only CONFIDENTIAL

CENTRAL INTELLIGENCE AGENCY

INFORMATION REPORT

COUNTRY Poland

SUBJECT Port of Gdanck Shippards: Northern Shippard (Stocznia Polnocna) and Gdanck Shippard (Stocznia Gdancka)/CP in the Shippards/Sabotage/Number of Employees/Accidents/Holm-Ostrow Island

PLACE ACQUIRED

DATE ACQUIRED (BY SOURCE)

25X1A

DATE (OF INFO.)

THIS DOCUMENT CONTAINS IMPORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES, WITHIN THE MEAN ING OF TITLE IS, SECTIONS 783 AND 784, OF THE U.S. CODE, AS AMENDED ITS TRANSMISSISM OR REVEL-LATION OF ITS CONTENTS TO OR EXCELPT OF AN UNAUTHORIZED PERSON IS CROMISETTO ST. LAS. THE SEPRODUCTION OF THIS REPORT IS PROMISEITED.

THIS IS UNEYALUATED INFORMATION



DATE DISTR. /4 Jun 1954

NO. OF PAGES

NO. OF ENCLS.

SUPP. TO REPORT NO.

<u>25X1X</u>

SOURCE

- 2. "The Gdsmak shippards are divided into two large units:
 - 1. Northern , hipyard (former Schichau, Stocznia Polinocna), and
 - 2. (dansk Shinyard (former Benziger-Stocznia Gdanska).
- 3. They both are subordinate to the Central Office of Shipbuilding (Centralne Biuro Budownictva Okretowego) which probably has, also, other shippurds under its orders. The office occupies premises in an old large building at the edge of the Gdansk shippard, but the entrance to it is from the street, close to the railway bridge in Robotnicza Street. One cannot enter the office iron inside of the shippard area. The entrance from the street is guarded.
- "Ta manother part of the same building there are the most important draughtsmen's workships, photographic laboratories etc. of the Gdansk shippard, where blue mints are prepared. This part of the building himself has a separate door opening to the inside of the shippard area, and one cannot reach it by entering the door leading to the outside street. Both doors are guarded, and special passes are regulared to enter the respective offices.
- 5. "The Polnocna and Gdanska Ethipyards form two superate administrative units; they have separate entrances and guards. There is no passage between them at all.
- 6. "The Polnocus chipyard has one entrance gate; the Gdanska shipyard has two gates and one more side-entrance. The Gdanska shipyard chiefly repairs and overhauls ships and beate, and the Polnocus shipyard is for ship building.

U.3. Officials Only

CONFIDENTIAL

SEE LAST WALL OF ABLICT CALLA CARES

This report is for the use within the USA of the Intelligence components of the Departments or Agencies indicated above. It is not to be transmitted overseas without the concurrence of the originating of the Office the Office of Residence 2001/03/04 CEA ROPS0-008098000500530082-0

Approved For Release 2001/03/04: CIA-RDP80-00809A000500530082-0

US OFFICIALS ONL' CONFIDENTIAL 25X1A

2

The Party organization in the shippards has a very important status because it is corresponsible for their production. Therefore, it is directly subordinate to the Town Committee of the Commist Party, which makes it equal in status to a Committee of a Town District.

Usually, Party Organizations in enterprises or offices are subordinate directly to a Town District Committee, and only through it to the Town Committee.

Bebotage

"For these reasons, the members running the Party Organization in the shippards are for the most part good Communists and trusted by the Party authorities. One of their duties is to stress the need for "Communist vigilance" against the enemy who would do its best to impede the production of the shippards. This is not an empty word. The percentage of sabotage is quite high in the rate of accidents in the shippards, and arrests among the personnel are very frequent, but they cannot stop the sabotage action. I am convinced that this action is carried on in an organized way, by some secret cell. The following is an example of a sabotage attempt which took place in 1952, and about which I learned from an UB official who was personally involved in it:

9. "A new ship (presumably a trawler) produced on a Soviet order was lying in the dock, ready to be lamiched. On the eve of lamiching the ship was tested for the less time; naturally, the testing test after checking on the details did not return to them again. Our UB official was on duty that night. He are not expected to enter the ship, but acting on some impulse he did not and started looking around in a nonemport way. He suddenly realized that screws were looke in one of the tulkheeds, which meant that if the ship were launched, she would immediately take water and sink. He gave an alarm and the damage was soon repaired. All the bulkheeds had been tested daring the day under the supervision of the UB; this meant that after the checkup screene had come back and loosened the screws. There were some arrests and an investigation, but the culprit was not found.

10. "Partly owing to the frequent asborage, partly to the same reasons which impace the production in all industrial catablishments run by the Communists, the production plans of the shippards are not fulfilled. I know for certain that they remained unfalfilled in 1952.

The Cdanska Shipyard is surrounded with a concrete fence which stretches from the Cdansk ghawerks up to the pontoon bridge over the canal around Holm (Ostrawica-Ostrow).

It forms a separate town composed of many buildings of all description: assembly halls, workshops, warshouses, offices, secial buildings otc. It has its own internal communication by railway (partly electrified) such, of course, motor transport.

"This shippard is divided into separate terrains of which there are five in all, named after the letters of the alphabet. I know that there is a terrain A and terrain B, but I do not know whether the others are called in a consecutive order (C, D and E) or not. The pass authorizing one to enter the shippard's area, states clearly in which terrain or terrains one is allowed to move. Permanent passes issued to the shippard personnel also specify the terrains, which means that even a person employed in the shippard cannot actually move freely in its area. A person not employed in the shippard and receiving a pass for a visit only, is obliged to obtain the signature on the pass of the shippard amployee whom he has some to visit.

13. "The administration building of the shippard is located near the second entrance gate, in the vicinity of the Health Center. The door to the

US OFFICIALS ONLY CONFIDENTIAL ,3.

building is guarded by a sentry. Here one finds the shippard management office, personnel office, financial department and a part of the draughtsmen's workshops (the main ones, as was already mentioned, are in the building partly occupied by the Central Office of Shipbuilding). The building itself is large and old.

- 14. "A bridge leads from the shipperd to the island of Holm-Ostrow. The bridge is guarded and a separate pass must be obtained to cross it. The controls on the way are so thick that a doctor, going in an ambulance to visit a patient on Holm, took nearly one hour to go through Gdanska shippard, the bridge and the island itself, as he was stopped by guards again and again and all his memerous passes (for himself, the driver and the car) were checked.
- 15. "The 'social buildings' serving the welfare of the shipyard personnel, are partly of new construction and well equipped, with baths, showers etc.
- 16. The shippard employs more than 10,000 people; about one-fifth of them are new workers who came as result of a large recruitment campaign started in the summer of 1952. In the shippard's area there is a vocational school training young shippard technicians, with a boarding establishment.
- living Quarters of Workers


 17. "Shipyard workers live partly in private femily flats, and partly in workers' hostels. One such hostel is on Sadowa Street in Gdansk, and a new workers' hostel was recently constructed in Wrzeszcz close to the MHD building (Town Retail Trade general store).
- Accidents

 The rate of accidents among the personnel is very high. Usually, they are either wound injuries or cases of chemical poisoning. There are also a great number of cases of food poisoning because the canteens for the personnel in the shippard area have rather primitive installations and lack a sufficient supply of refrigerators.
- "Another reason for illness is the faulty system of water supply and of sewage. The Poles, taking over the shipyards, found German installations on the spot. Some or these installations were damaged or destroyed. These had to be repaired or replaced and also new ones laid. The trouble was that no one could say how these old installations ran underground, and no plane were available. As a result the new installations have been laid in a rather chaotic manner, and it has been discovered that in many places water-supply pipes run very close to the sewage pipes, which creates a danger of infection. There may well be many other such danger spots, as nobody has any idea how the pipes run and intercross under the surface.
- 20. "Accidents and safety-at-work precautions are dealt with by the BHIB office (Biuro Higieny I Bezpieczenstwa Pracz- Office of Hygiens and Safety at Work) accomplated in a separated building. The snippard also has an ambulance service of its own (Posetowie Ratunkowe) under the combined control of BHIP and Health Center. The ambulance service has its garage close to the medical surgery.
- 21. The shipperd has its own fire service. In case of a larger conflagration, the fire service of the Gdansk Harbor may be called.
- 22. There are constant delays in the production of the shippard. As a rule every job is delayed by one month.
- The Polnocna Shipyard (former Schichau)copes with the construction of new

US OFFICIALS VALY
CONFIDENTIAL

Approved For Release 2001/03/04: CIA-RDP80-00809A000500530082-0

US OFFICIALS ONLY CONFIDENTIAL



sea-going craft. It is here that the chips of the 'Soldek' type are built. Incidentally, the stakhanovite (fmu) Soldek after whom the type was called, is still working in Foliacua shipyard in one of the large workshops as a 'Trager' specialist. I knew him quite well; he is not a Communist, simply a good worker and quite a nice man.

- 24. This shippard is also like a large city with lots of buildings. I do not know its setup very well, but the 'social buildings', canteens, water installations, and accidents in Gdanska shippard apply here as well. There are a great number of quite new assembly halls and workshops in Polnocan shippard, which is still being developed and enlarged in the northern direction.
- 25. "The ships Warszawa and Nown Huta were constructed in the Gdanska shipyard.

Holm-Outrow Island Base

26. Holm-Outrow island is more difficult to reach than any other part of the shippards. It served formerly as a base for Garman U-boats. Its buildings have been mostly destroyed or damaged during world war II. Now / 1953 / they are being repaired and new buildings are being erected. It is said that in the future, Holm is to belong to the Northern shippard as a naval shippard. Already it is treated as a military area. The former U-boat base is being reconstructed.

- 27. "On the shore of the island opposite the chemical factory there is a reserve wharf for livestock.
- 28. "There are also on Holm various workshops and establishments of 'sea engineering' (Inzymieria Norska) belonging to the MECIP enterprise (readslebiorstwo Robot Czernanych I Podwodnych).

Receiving Issuing Base

'Very important for the work of the shippards is the so-called 'receiving-issuing base' (Baza Zdawczo Odbiorcza) established on Holm-Ostrow. This base occupies a number of buildings. Its head is a certain Captain (fmu) Choincwski. The work of the base concists of taking care of the first and last stage of every order for the Gdansk shippards. First, it receives the order with all necessary specifications. Then, when the job passes to the appropriate sections of the shippards, the base has nothing to do until the end when the work has been done. At that final stage the duty of the base is to give its ultimate 0.4. to the ship or boat before she actually leaves the shippards. The base carries out final trials and testing, including a trial trip.

The base has at its disposal a provisional crew for carrying out the trial trips. About 8% of this crew are not sailors, but UB agents who only take room on the boats without giving any practical help. These trial trips are no fun at all for the sailors of the crew because of the disconfort caused by the overcrowding of the tested boats. Also, no one wants to take the final responsibility for passing the boat as satisfactory, and there is quite an excunt of friction about it. This avoidance of responsibility is one of the reasons why the boats are not tested by smaller teams but are usually boarded by the entire provisional crew, who in consequence have hardly room to move around. Also, the interference of UB men on trial trips is even greater than on other occasions.

LIBRARY SUBJECT & AREA CODES 743.43 55M 9/743.41 554 107.75 55M 4-12/743.43 55M US OFFICIALS ONLY 55M 762,51 853.4 CONFIDERTIAL 55M 2-5/743.41 55M

作品にはいる